









Setting up CADconform certification – CADconform User Manager

Copy the cell library with your existing watermark and logo cells to the (by default)
C:\ProgramData\Bentley\MicroStation CONNECT
Edition\Configuration\WorkSpaces\BHPIO\Standards\Cell
I folder.

WorkSpaces > BHPIO > Standards > Cell

Name

-  BHPBIO-AreaPatterning.cel
-  BHPBIO-General legacy.cel
-  BHPBIO-General.cel
-  BHPBIO-MobileEquipment.cel
-  BHPBIO-SafetySymbols.cel
-  BHPBIO-Scalebars.cel
-  BHPBIO-Target.cel
-  Project Cells.cel


Open the Administration dialog box and go to
Manage Users.


CADconform



Open Administration

Server Settings (All Users)

 Manage Users

 Edit Server Version

Select the BHPIO default user.

Open the Certifying tab and set your watermark up as per the screenshot.

The Marker Cell should be T-BHP MARKER and the Certification Cell should be your approved company watermark cell.

Click Save to exit the User Manager, now when you log back into CADconform you will be able to watermark drawings.

The screenshot shows the 'User Manager' application window. At the top, there's a 'File' menu and a table with columns 'Login', 'Full Name', and 'Type'. The table contains two entries: 'BHPIO' (Group) and 'admin' (User). To the right of the table are buttons for 'New User', 'New Group', and 'Delete'. Below the table is a 'Login Name' field with 'BHPIO' entered. At the bottom, there are tabs for 'Tools', 'Administration', 'Locking', 'Certifying', and 'Digitally Sign'. The 'Certifying' tab is selected and highlighted with a red box. Inside this tab, there are two checked options: 'Place Certify Markers' and 'Certify Drawings'. Below these are three fields: 'Cell Library' (set to 'Project Cells.cel'), 'Certification Marker Cell' (set to 'T-BHP MARKER'), and 'Certification Cell' (set to 'CM WATERMARK'). Each of these three fields has a red box around it.

Login	Full Name	Type
BHPIO		Group
admin	admin	User

Login Name: BHPIO

Tools Administration Locking **Certifying** Digitally Sign

☒ Place Certify Markers ☒ Certify Drawings

Cell Library: Project Cells.cel ...

Certification Marker Cell: T-BHP MARKER ...

Certification Cell: CM WATERMARK ...

Contacting BHP

For any queries concerning this document, please contact:

Asset GTS Engineering Standards

Email: spo@bhp.com